



ECS, Inc. International  
15351 W. 109<sup>th</sup> St  
Lenexa, KANSAS, 66219 USA  
[www.ecsxtal.com](http://www.ecsxtal.com)  
913-782-7787  
1-800-237-1041  
Fax: 913-787-6991

July 9, 2021

## **END OF LIFE NOTICE**

**PCN #: 070921-VC-TXO-35SM**

**Description and Purpose of Change:** Due to fire at IC supplier (AKM) we can no longer support this oscillator series. We have looked for alternate IC options but do not have a suitable replacement and the IC maker has recently decided that this IC will not return to production has been discontinued. Unfortunately, there is not a direct replacement for this package, possible alternatives are listed below. Please work with your ECS sales contact for any questions about replacement options.

**Products Affected:**

ECS Model Number	ECS Standard Part Numbers
VC-TXO-35SM	VC-TXO-35SM-120-B-TR
+3.0V	VC-TXO-35SM-128-B-TR
	VC-TXO-35SM-128-D-TR
Possible Alternative Series	VC-TXO-35SM-130-B-TR
ECS-VTXO-5032CS (Digital Compensation)	VC-TXO-35SM-130-D-TR
	VC-TXO-35SM-144-B-TR
	VC-TXO-35SM-160-B-TR
	VC-TXO-35SM-168-B-TR
	VC-TXO-35SM-192-B-TR
	VC-TXO-35SM-192-D-TR
	VC-TXO-35SM-194.4-B-TR
	VC-TXO-35SM-200-B-TR
	VC-TXO-35SM-245.535-D-TR
	VC-TXO-35SM-260-B-TR

We apologize for the inconvenience and thank you for your understanding and cooperation. If you have questions please contact your ECS Sales, Representative or Distributor in your area.

Dan Kelly  
VP of Engineering  
ECS Inc. International